

Mine Name: Anval 1&2

State of Utah DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R. STYLER Executive Director JOHN R. BAZA Division Director

Inspection Report Minerals Regulatory Program Date: August 20, 2008

Operator Name: Steven Gale Inspector(s): Tom Munson & Brett Gregory Other Participants: None		Inspection Date: 07-23-2008 Time: 11:00 am-11:30 am Mine Status: Active							
						Elements of Inspection	Evaluated	Comment	Enforcement
1.	Permits, Revisions, Transfer, Bonds	\boxtimes	\boxtimes						
2.	Public Safety (shafts, adits, trash, signs, highwalls)								
3.	Protection of Drainages / Erosion Control								
4.	Deleterious Material								
5.	Roads (maintenance, surfacing, dust control, safety)								
6.	Concurrent Reclamation	\boxtimes							
7.	Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)								
8.	Water Impoundments								
9.	Soils								
10.	Re-vegetation								
11.	Air Quality								
12.	Other	oxtimes	\boxtimes						

Bond Renewal Date: now

Bond Amount: \$1,600

Permit fee up to date

Permit Number: S0010038

Purpose of Inspection:

The purpose of this inspection was to evaluate the mining operation and validate the size of the disturbance. The operator has also requested that his bond remain at a reduced amount based on the amount of disturbance. The minimum bond for an acre of disturbance is \$6,300.

Inspection Summary:

The site has expanded slightly. We attempted to GPS the site but due to problems with the GPS this was not possible. The GPS map was generated was in 2006 and the disturbance was approximately .4 acres. There was evidence of oil spills on site.

Conclusions and Recommendations:

The operator be required to post a larger bond and fix the machinery to avoid any further spills.

Inspector's Signature

TM:pb

cc: ed_ginouves@blm.gov

O:\M001-Beaver\S0010038-Anval\inspections\ins-07232008.doc